

COUNTY Lewis
RESOURCE # Lw-90
RELATED GROUP #
EVALUATION S
SHPO EVALUATION S
DESTROYED

SHPO EVALUATION 5
DESTROYED

| <u>TYPE</u> | <u>MATERIAL</u> |
|----------------|---------------------|
| 2 / Continuous | 0/ Unknown original |
| / | / replacement |

| | |
|------------------------------|-------------|
| <u> </u> I/ Weatherboard | original |
| <u> </u> Y / Vinyl siding | replacement |

| | |
|-----------------|---------------------------------|
| A / Gable, Side | 7/ Standing seam metal original |
| / | / replacement |

Write resource # on back of all prints.

W / 3 / Frame original
 / / subsequent


R / first / second / third



This house, likely built c. 1860-1880, is a one-and-a-half story, four-bay frame residence now clad in vinyl siding. On the façade, a small gable has decorative “gingerbread” in the eaves and decorative rake boards. The house has a wrap-around porch supported by round Doric columns with a wooden railing running between the posts. Windows in the house are replacement 1/1 vinyl windows. On the east elevation, a one-room addition has been added to the house, blocking off the wrap-around porch. The house and porch roofs are both standing-seam metal. Latticework beneath the porch obscures the foundation material, which is assumed to be stone. The front door is a later replacement, but the original transom above remains intact. Several outbuildings are located on the property.

| 25. SUPPORT RESOURCES: | SITE PLAN KEY | FUNCTION | CONSTRUCTION DATE | METHODMATERIAL |
|------------------------|---------------|------------------|-------------------|----------------|
| Shed | A | Storage | c. 1860-1880 | W/3/ Frame |
| Barn | B | Agricultural use | c. 1860-1880 | W/3/ Frame |
| Barn | C | Agricultural use | c. 1860-1880 | W/3/ Frame |

26. SITE PLAN (Complete if #25 was answered).



27. MAP (Scan or attach copy of map showing exact location of resource)

